



- Asbestos air sampling location
 - Asbestos, TSP/metals sampling and ambient dust monitoring location
 - Former site railroad (removed)
- STATUS**
- Debris remains, awaiting disposal
 - Site boundary

- Building D**
- STATUS**
- Awaiting asbestos abatement
 - Building demolished
 - Decontamination in progress
 - Demolition in progress

Basemap source: Esri



EAGLE ZINC OPERABLE UNIT 1
MONTGOMERY COUNTY, HILLSBORO, ILLINOIS

DEMOLITION PROGRESS TRACKING
March 04 2015
BUILDING D DETAIL

EPA REGION 5 RAC 2 | REVISION 0 | March 2015

